


Parallel Groove Clamp



Parallel groove connector is used for connecting or branching overhead conductors.Extruded create a high strength clamp.slotted holes allow adjusting for varying conductors on each side. its type test is accordance with IEC61238-1.Shape Body made from extruded copper or brass and bolt and spring wwasher are made of steel with hot dip galvanized plating.

TABLE

Conductor Size mm ²	Bolt	CAT NO.
6-50mm ²	2xM8x45	MCBPGC-6
10-95mm ²	3xM8x50	MCBPGC-10
25-18mm ²	3xM10x60	MCBPGC-25
35-24mm ²	3xM10x70	MCBPGC-35